



Aluminum Canopy Systems


EAST COAST TVM, LLC

P.O. BOX 4008

FLORENCE, SC 29502

Phone: 843.346.3885

Fax: 843.346.3913



I_x : 7.274 in⁴

I_y : 13.638 in⁴

W: 3.160 lb/ft

S_x : 3.637 in³

S_y : 4.094 in³

CG_x : 2.000 in

CG_y : 3.331 in


4" x 6" x .125" DRAIN BEAM



Aluminum Canopy Systems

EAST COAST TVM, LLC

P.O. BOX 4008
FLORENCE, SC 29502
Phone: 843.346.3885
Fax: 843.346.3913



I_x : 9.125 in ⁴	I_y : 25.503 in ⁴	W: 3.646 lb/ft
S_x : 4.563 in ³	S_y : 5.605 in ³	
CG_x : 2.000 in	CG_y : 4.550 in	
4" x 8" x .125" DRAIN BEAM		



Aluminum Canopy Systems


EAST COAST TVM, LLC

P.O. BOX 4008

FLORENCE, SC 29502

Phone: 843.346.3885

Fax: 843.346.3913



$I_x: 14.728 \text{ in}^4$

$I_y: 20.007 \text{ in}^4$

$W: 3.664 \text{ lb/ft}$

$S_x: 4.908 \text{ in}^3$

$S_y: 5.620 \text{ in}^3$

$CG_x: 3.001 \text{ in}$

$CG_y: 3.560 \text{ in}$


6" x 6" x .156" DRAIN BEAM



Aluminum Canopy Systems

EAST COAST TVM, LLC

P.O. BOX 4008
FLORENCE, SC 29502
Phone: 843.346.3885
Fax: 843.346.3913



$I_x: 30.977 \text{ in}^4$

$I_y: 39.271 \text{ in}^4$

$W: 5.538 \text{ lb/ft}$

$S_x: 10.326 \text{ in}^3$

$S_y: 8.785 \text{ in}^3$

$CG_x: 3.000 \text{ in}$

$CG_y: 4.470 \text{ in}$


6" x 8" x .188" DRAIN BEAM



Aluminum Canopy Systems

EAST COAST TVM, LLC

P.O. BOX 4008
FLORENCE, SC 29502
Phone: 843.346.3885
Fax: 843.346.3913



$I_x: 39.506 \text{ in}^4$

$I_y: 81.954 \text{ in}^4$

$W: 7.214 \text{ lb/ft}$

$S_x: 13.169 \text{ in}^3$

$S_y: 14.876 \text{ in}^3$

$CG_x: 3.000 \text{ in}$

$CG_y: 5.509 \text{ in}$

6" x 10" x .220" DRAIN BEAM



Aluminum Canopy Systems


EAST COAST TVM, LLC

P.O. BOX 4008

FLORENCE, SC 29502

Phone: 843.346.3885

Fax: 843.346.3913



$I_x: 45.795 \text{ in}^4$

$I_y: 123.793 \text{ in}^4$

$W: 7.991 \text{ lb/ft}$

$S_x: 15.265 \text{ in}^3$

$S_y: 18.632 \text{ in}^3$

$CG_x: 3.000 \text{ in}$

$CG_y: 6.644 \text{ in}$

6" x 12" x .250" DRAIN BEAM